



Montageanleitung










Exploded View









Fittings

 A x 24 M6 x 35 mm	 B x 24 ø15 x 9.5 mm	 C x 34 ø8 x 30 mm	 D x 14 ø4 x 35 mm	 E x 4
 F x 8 M4 x 12 mm	 G x 4	 H x 4 ø10 x 2 mm	 I x 30 ø3 x 12 mm	 J x 26 ø3.5 x 12 mm
 K x 8 M6 x 11 mm	 L x 4	 M x 2	 N x 2	 CL x 2 300 mm
 CR x 2 300 mm	 DL x 2 300 mm	 DR x 2 300 mm		



1.








2.







3.





4.





5.





6.





7.






8.






9.




10.



11.



12.





XX=YY



I x 30
φ3 x 12 mm

13.



E x 2



F x 4
M4 x 12 mm



G x 4





H x 4
φ10 x 2 mm





J x 8
φ3.5 x 12 mm

14.




 **K x 4**
M6 x 11 mm

15.




 **K x 4**
M6 x 11 mm

16.






L x 4




17.





18.




19.






20.








21.




22.



23.



24.



25.

