

ASSEMBLING INSTRUCTION


1 X1PC



2 X1PC



3 X1PC



A X1PC



B X4PCS



m6*45


C X5PCS




D X1PC



1



2



3

